

Cerabar M PMC51

Digital Pressure Transmitter



- ⊙ **Pressure: up to 40bar**
- ⊙ **Overload-resistant high purity ceramic sensor**
- ⊙ **Easy menu-guided commissioning via on site display**
- ◇ **Process connections: threads, flanges or hygienic connections**
- ◇ **For process pressure monitoring up to SIL2**

Accuracy: $\pm 0.15\%$

